


Parametric Modeling

With

Pro/ENGINEER® Wildfire 3.0

An Introduction to Pro/ENGINEER WILDFIRE



Randy H. Shih

Oregon Institute of Technology

SDC
PUBLICATIONS

Schroff Development Corporation

www.schroff.com
www.schroff-europe.com

Table of Contents

Preface

Acknowledgments

Introduction

Introduction	Intro-2
Development of Computer Geometric Modeling	Intro-2
Feature-Based Parametric Modeling	Intro-6
Getting Started with Pro/ENGINEER	Intro-7
Starting Pro/ENGINEER	Intro-7
Pro/ENGINEER Screen Layout	Intro-8
Pull-down menus	Intro-9
Standard Toolbar	Intro-9
Message area	Intro-9
Graphics display area	Intro-9
Datum Toolbar	Intro-9
Navigator	Intro-10
Web Browser	Intro-10
Single Line Help	Intro-10
Mouse Buttons	Intro-11
Model Tree window and Menu Manager	Intro-12
On-Line Help	Intro-13
Leaving Pro/ENGINEER	Intro-14
Creating a CAD files folder	Intro-14

Chapter 1

Parametric Modeling Fundamentals

Introduction	1-2
The Adjuster design	1-3
Starting Pro/ENGINEER	1-3
Step 1: Units and Basic Datum Geometry Setups	1-5
Units Setup and Pro/ENGINEER Menu Structure	1-5
Tree Structure	1-6
Adding the First Part Features — Datum Planes	1-7
Step 2: Determine/Setup the Base Solid Feature	1-8
Sketching plane – It is an XY CRT, but an XYZ World	1-9
Defining the Sketching Plane	1-10
Defining the Orientation of the Sketching Plane	1-11
Step 3: Creating 2D rough sketches	1-13
Shape Before Size – Creating Rough Sketches	1-13
The Pro/ENGINEER SKETCHER and INTENT MANAGER	1-14

Graphics Cursors	1-15
Geometric Constraint Symbols	1-16
Dynamic Viewing Functions	1-17
Step 4: Apply/modify constraints and dimensions	1-18
Modifying the dimensions of the sketch	1-21
Repositioning Dimensions	1-23
Step 5: Completing the Base Solid Feature	1-24
The Third Dynamic Viewing Function	1-25
Display Modes: Wireframe, Shaded, Hidden Edge, No Hidden	1-26
Step 6: Adding additional features	1-27
Creating a CUT Feature	1-31
Creating the 2D Section of the CUT Feature	1-32
Save the Part and Exit	1-35
Questions	1-36
Exercises	1-37

Chapter 2

Constructive Solid Geometry Concepts

Introduction	2-2
Binary Tree	2-3
Project: <i>Locator</i>	2-4
Modeling Strategy - CSG Binary Tree	2-5
Starting Pro/ENGINEER	2-6
Units Setup	2-7
Adding the First Part Features — Datum Planes	2-8
Base Feature	2-9
Creating a 2D parametric section	2-11
Creating the Second Solid Feature	2-14
Creating the 2D sketch	2-15
Creating a CUT Feature	2-18
Creating the 2-D section	2-19
Redefine a Feature Element	2-23
Creating a Placed HOLE Feature	2-25
Creating the Final Feature	2-28
Creating the 2-D Section	2-29
Questions	2-32
Exercises	2-33

Chapter 3

Model History Tree

Introduction	3-2
The <i>L-Support</i> Design	3-3
Starting Pro/ENGINEER	3-3
Modeling Strategy	3-6
2-D Sketching	3-7
Set up the Pro/ENGINEER Default View	3-9
Add the Second Solid Feature	3-10
Renaming the Part Features	3-14
Expanding the Model Tree Listing	3-15
Creating a Placed HOLE Feature	3-16
Creating a Rectangular Cutout	3-18
Examining the Model History	3-22
History-based Part Modifications	3-23
Modifying Dimensional Values	3-24
Modifying the 2-D Section of the Base Feature	3-26
Questions	3-28
Exercises	3-29

Chapter 4

Parametric Relations and Constraints

Geometric Construction and Constraints	4-2
The <i>Gasket</i> Design	4-2
Modeling Strategy	4-3
Starting Pro/ENGINEER	4-4
Using the 2D Sketcher in 3-D Orientation	4-5
Creating the Base Feature	4-5
Implicit Geometric Relationships	4-7
Disable/Enable Constraints	4-8
Create and Divide a Circle	4-10
Create a closed region Sketch	4-11
Modify Geometry by Drag-and-Drop	4-12
Controlling Geometric Relationships	4-13
REDO and UNDO	4-15
Using Sketcher Points	4-16
Deleting Geometric Constraints	4-17
Weak Dimensions and Constraints	4-18
Completing the Base Feature	4-19
Using the Offset Loop Option to create a CUT feature	4-20
Parametric Relations and Geometric Constraints	4-23
Create a Simple Plate Design	4-23
Using a Sketch file	4-24

Dimensional Values and Dimensional Variables	4-25
Saving the Sketch File and Exit the Sketcher Mode	4-27
Sketch Files vs. Part Files	4-28
Starting a new Pro/ENGINEER Part	4-28
Creating the Base Feature	4-29
Placing the 2-D Sketch	4-31
Display the Parametric Relations	4-33
Complete the Extrusion Feature	4-34
Parametric Relations at different levels	4-35
Questions	4-39
Exercises	4-40

Chapter 5

Parent/Child Relationships

Introduction	5-2
The <i>U-Bracket</i> Design	5-3
Preliminary Modeling Considerations	5-3
Starting Pro/ENGINEER	5-4
Creating the Base Feature	5-5
Creating a and transform a Rough Sketch	5-6
Creating the Second Solid Feature	5-13
Creating a CUT Feature	5-15
Creating the CENTER_DRILL Feature	5-16
Examining the Parent/Child Relationships	5-19
Display Parent/Child Info	5-20
Modify a Parent Dimension	5-21
A Design Change	5-22
Feature Suppression	5-23
Creating the Circular Cut Feature	5-24
Listing Suppressed Features	5-25
Reactivate the CENTER_DRILL Feature	5-26
Reroute the CENTER_DRILL Feature	5-27
Suppress the RECT_CUT Feature	5-28
Questions	5-29
Exercises	5-30

Chapter 6

Datum Features, 3D Annotation and Part Drawings

Datum Features	6-2
3D Annotation	6-2
Drawings from Parts	6-2
The <i>Rod-Guide</i> Design	6-3

Modeling Strategy	6-4
Starting Pro/ENGINEER	6-5
Creating the Base Feature	6-5
Creating a Datum Axis	6-8
Creating a Datum Plane at an angle	6-9
Create the next Solid Feature	6-11
Creating a Datum Plane Using the Filter option	6-13
Creating a Placed Feature	6-17
Add four holes to the Base Feature	6-18
3D Annotation	6-20
Creating a Multi-View Drawing using a Drawing Template	6-25
Creating Another Multi-View Drawing	6-27
Adding a Primary Main View	6-28
Adding a Projected Auxiliary View	6-29
Adjust the Overall Drawing Display	6-30
Displaying Feature Dimensions	6-32
Dimension Appearances	6-33
Displaying Centerlines	6-35
Displaying Remaining Annotations	6-36
Annotation Appearances	6-37
Adding/Deleting Dimensions – Feature/Driven Dimensions	6-38
Adding an Isometric View	6-41
Questions	6-44
Exercises	6-45

Chapter 7

Symmetrical Features in Designs

Symmetrical Features in Designs	7-2
A Revolved Part: <i>Wheel</i>	7-2
Modeling Strategy - A Revolved Design	7-3
Starting Pro/ENGINEER	7-4
Creating the Base Feature	7-4
Creating Diameter Dimensions	7-6
Modify the values of Dimensions	7-7
Completing the Revolved Feature	7-8
Using the Mirror Option	7-9
Adding a Radial Hole Feature	7-10
Create a Circular Pattern	7-12
Parametric Relations	7-13
Creating a Multi-View Part Drawing	7-15
Adding the Primary Main View	7-16
Adding a Projected Sectional View	7-17
Modify the Overall Drawing Display	7-20
Displaying Feature Dimensions	7-21

Adding Additional Dimensions – Driven Dimensions	7-23
Dimension Appearances	7-24
Displaying Centerlines	7-25
Adjusting the Length of Centerlines	7-26
Creating Additional Centerlines	7-27
Using the Drawing Options	7-29
Associative Functionality – Modifying Feature Dimensions	7-30
Bi-Directional Associative Functionality	7-32
Questions	7-33
Exercises	7-34

Chapter 8

Three Dimensional Construction Tools

Introduction	8-2
A Thin-Walled Part: <i>Dryer Housing</i>	8-2
Modeling Strategy	8-3
Starting Pro/ENGINEER	8-4
Creating the Base Feature	8-5
Create the Revolved Part	8-6
Creating the second Feature	8-7
Create a Blend Feature	8-9
Creating 2-D Blend Sections	8-11
Create 3-D Rounds and Fillets	8-15
Creating a Shell Feature	8-16
Create a Pattern Leader	8-18
Create a Rectangular Pattern	8-20
Creating a Sweep Feature	8-22
Define the Sweep Trajectory	8-22
Define the Sweep Section	8-24
Questions	8-26
Exercises	8-27

Chapter 9

Advanced Modeling Tools

Introduction	9-2
Summary of Modeling Considerations	9-2
The <i>BRACKET</i> Design	9-2
Modeling Strategy	9-3
Starting Pro/ENGINEER	9-4
Creating the Base Feature	9-5
Using the CUT Option to Create a <i>Boolean INTERSECT</i>	9-6
Creating a Reference Plane	9-10

Creating Another Extrude Feature	9-11
Using the Draft Angle Tool	9-14
Create the Top Cylindrical Feature	9-16
Create the Hole through the Cylinder	9-18
Create a Sketched Hole on the Base Feature	9-18
Using the Copy Function to Create a Mirror Feature	9-21
Creating Chamfers	9-22
Adding <i>SIMPLE</i> Rounds and Fillets - Edges	9-23
Adding <i>Advanced</i> Rounds and Fillets - Surfaces	9-24
Adding the Last Feature	9-26
Changing Model Colors	9-27
Saving the Part	9-28
Questions	9-30
Exercise	9-31

Chapter 10

Assembly – Putting It All Together

Introduction	10-2
The <i>BRACKET</i> Assembly	10-2
Assembly Modeling Methodology	10-3
Additional Parts	10-4
(1) <i>Base Plate</i>	10-4
(2) <i>Bushing</i>	10-4
(3) <i>Cap Screw</i>	10-5
Create a Subassembly	10-6
Retrieving the <i>Bracket</i> Component	10-7
Retrieving the <i>Bushing</i> Component	10-7
Placement Constraints	10-8
Placing the <i>Bushing</i>	10-9
Create the Second Placement Constraint	10-11
Create the <i>Bracket</i> Assembly Model	10-13
Base Component	10-14
Retrieving the <i>Bracket-Bushing</i> Subassembly	10-15
Placing the <i>Bracket-Bushing</i> Subassembly	10-15
Placing the <i>Cap Screws</i>	10-17
Exploding the Assembly	10-19
Bi-directional Associative Functionality	10-21
Conclusion	10-23
Questions	10-24
Exercise	10-25

INDEX

Notes: