


ANSYS[®] Workbench Tutorial

***Structural & Thermal Analysis using the
ANSYS Workbench Release 13 Environment***



Kent L. Lawrence

Mechanical and Aerospace Engineering
University of Texas at Arlington

SDC
PUBLICATIONS

www.SDCpublications.com

Schroff Development Corporation

CONTENTS

INTRODUCTION

| | |
|-----------------------------------|-----|
| I-1 OVERVIEW | I-1 |
| I-2 THE PROCESS | I-1 |
| I-3 THE TUTORIALS | I-2 |
| I-4 THE ANSYS WORKBENCH INTERFACE | I-3 |
| I-5 SUMMARY | I-6 |

CHAPTER 1 – SOLID MODELING FUNDAMENTALS

| | |
|------------------------------|------|
| 1-1 OVERVIEW | 1-1 |
| 1-2 INTRODUCTION | 1-1 |
| 1-3 TUTORIAL 1A - EXTRUSION | 1-2 |
| 1-4 TUTORIAL 1B – REVOLUTION | 1-10 |
| 1-5 TUTORIAL 1C – SWEEP | 1-12 |
| 1-6 SKETCHING | 1-14 |
| 1-7 SUMMARY | 1-17 |
| 1-8 PROBLEMS | 1-18 |

CHAPTER 2 – PLACED FEATURES, ASSEMBLY

| | |
|---|------|
| 2-1 OVERVIEW | 2-1 |
| 2-2 INTRODUCTION | 2-1 |
| 2-3 TUTORIAL 2A - ADDING A HOLE TO THE EXTRUSION | 2-2 |
| 2-4 TUTORIAL 2B - ADDING A ROUND TO THE EXTRUSION | 2-6 |
| 2-5 TUTORIAL 2C - ADDING A CHAMFER TO THE EXTRUSION | 2-8 |
| 2-6 TUTORIAL 2D – PATTERNS | 2-9 |
| 2-7 TUTORIAL 2E – CLEVIS ASSEMBLY | 2-13 |
| 2-8 TUTORIAL 2F – ALTERNATE SOLID MODELER | 2-18 |
| 2-9 SUMMARY | 2-20 |
| 2-10 PROBLEMS | 2-21 |

CHAPTER 3 – MODELING TECHNIQUES

| | |
|---|------|
| 3-1 OVERVIEW | 3-1 |
| 3-2 INTRODUCTION | 3-1 |
| 3-3 TUTORIAL 3A – PARAMETERS | 3-2 |
| 3-4 OTHER CAD SYSTEMS | 3-9 |
| 3-5 SURFACE AND LINE MODELS | 3-9 |
| 3-6 TUTORIAL 3B – PLANAR SURFACE MODELS | 3-10 |
| 3-7 TUTORIAL 3C – 3D SURFACE MODELS | 3-11 |
| 3-8 TUTORIAL 3D – LINE MODELS | 3-13 |
| 3-9 SUMMARY | 3-19 |
| 3-10 PROBLEMS | 3-20 |

CHAPTER 4 – ANSYS MECHANICAL I

| | |
|--|------|
| 4-1 OVERVIEW | 4-1 |
| 4-2 INTRODUCTION | 4-1 |
| 4-3 TUTORIAL 4A – PLATE WITH CENTRAL CIRCULAR HOLE | 4-2 |
| 4-4 TUTORIAL 4B – PLATE WITH CENTRAL SQUARE HOLE | 4-23 |
| 4-5 SUMMARY | 4-34 |
| 4-6 PROBLEMS | 4-35 |

CHAPTER 5 - ANSYS MECHANICAL II

| | |
|---|------|
| 5-1 OVERVIEW | 5-1 |
| 5-2 INTRODUCTION | 5-1 |
| 5-3 TUTORIAL 5A – CYLINDRICAL PRESSURE VESSEL | 5-1 |
| 5-4 TUTORIAL 5B - BRACKET | 5-12 |
| 5-5 TUTORIAL 5C – CLEVIS ASSEMBLY | 5-17 |
| 5-6 SUMMARY | 5-25 |
| 5-7 PROBLEMS | 5-26 |

CHAPTER 6 – WIZARDS & TOOLS

| | |
|--|------|
| 6-1 OVERVIEW | 6-1 |
| 6-2 INTRODUCTION | 6-1 |
| 6-3 TUTORIAL 6A – STATIC LOADINGS – DUCTILE MATERIALS | 6-1 |
| 6-4 TUTORIAL 6B - STATIC LOADINGS – BRITTLE MATERIALS | 6-10 |
| 6-5 TUTORIAL 6C - FATIGUE LOADINGS – DUCTILE MATERIALS | 6-15 |
| 6-6 SUMMARY | 6-22 |
| 6-7 PROBLEMS | 6-23 |

CHAPTER 7 – HEAT TRANSFER & THERMAL STRESS

| | |
|--|------|
| 7-1 OVERVIEW | 7-1 |
| 7-2 INTRODUCTION | 7-1 |
| 7-3 HEAT TRANSFER | 7-1 |
| 7-4 TUTORIAL 7A – TEMPERATURE DISTRIBUTION IN A CYLINDER | 7-2 |
| 7-5 THERMAL STRESS I | 7-8 |
| 7-6 TUTORIAL 7B – UNIFORM TEMPERATURE CHANGE | 7-8 |
| 7-7 THERMAL STRESS II | 7-19 |
| 7-8 TUTORIAL 7C – THERMAL STRESS IN A CYLINDER | 7-20 |
| 7-9 SUMMARY | 7-25 |
| 7-10 PROBLEMS | 7-26 |

CHAPTER 8 – SURFACE & LINE MODELS

| | |
|---|------|
| 8-1 OVERVIEW | 8-1 |
| 8-2 INTRODUCTION | 8-1 |
| 8-3 TUTORIAL 8A – SHEET WITH CIRCULAR HOLE – PLANE STRESS | 8-2 |
| 8-4 TUTORIAL 8B – PRESSURE VESSEL | 8-12 |
| 8-5 TUTORIAL 8C – BRACKET | 8-17 |
| 8-6 TUTORIAL 8D – LINE-BODY MODEL | 8-23 |
| 8-7 SUMMARY | 8-28 |
| 8-8 PROBLEMS | 8-29 |

LESSON 9 – NATURAL FREQUENCIES & BUCKLING LOADS

| | |
|--|------|
| 9-1 OVERVIEW | 9-1 |
| 9-2 INTRODUCTION | 9-1 |
| 9-3 TUTORIAL 9A – SIMPLY SUPPORTED BEAM FREQUENCIES | 9-1 |
| 9-4 TUTORIAL 9B – NATURAL FREQUENCIES OF A CHIME | 9-8 |
| 9-5 TUTORIAL 9C – NATURAL FREQUENCIES OF AN ASSEMBLY | 9-14 |
| 9-6 BUCKLING LOADS | 9-18 |
| 9-7 TUTORIAL 9D – FIXED-FREE COLUMN (FLAGPOLE) | 9-18 |
| 9-8 TUTORIAL 9E – BUCKLING OF A PINNED-PINNED COLUMN | 9-22 |
| 9-9 TUTORIAL 9F – BUCKLING OF A BUILT-UP STRUCTURE | 9-27 |
| 9-10 SUMMARY | 9-30 |
| 9-11 PROBLEMS | 9-32 |

REFERENCES
