




Engineering Design

with SolidWorks 2012

and Video Instruction

A Step-by-Step Project Based Approach Utilizing 3D Solid Modeling

Introductory Level ♦ Tutorial Style ♦ Video Instruction



David C. Planchard & Marie P. Planchard, CSWP

SDC
PUBLICATIONS

www.SDCpublications.com

Schroff Development Corporation

Table of Contents

| | |
|---|------------|
| Introduction | I-1 |
| About the Cover | I-2 |
| About the Authors | I-2 |
| Acknowledgements | I-3 |
| Contact the Authors | I-3 |
| Note to Instructors | I-3 |
| Trademarks, Disclaimer and Copyrighted Material | I-3 |
| References | I-4 |
| Table of Contents | I-6 |
| Overview of Projects | I-14 |
| What is SolidWorks? | I-19 |
| About the Book | I-21 |
| Windows Terminology in SolidWorks | I-22 |
| | |
| Project 1 - Fundamentals of Part Modeling | 1-1 |
| Project Objective | 1-3 |
| Project Situation | 1-4 |
| Project Overview | 1-6 |
| File Management | 1-7 |
| Start a SolidWorks 2012 Session | 1-9 |
| Understand the SolidWorks User Interface and CommandManager | 1-10 |
| Menu bar toolbar | 1-10 |
| Menu bar menu | 1-10 |
| Drop-down menu | 1-11 |
| Right-click | 1-11 |
| Consolidated toolbar | 1-12 |
| System feedback icons | 1-12 |
| Confirmation Corner | 1-12 |
| Heads-up View toolbar | 1-13 |
| SolidWorks CommandManager | 1-15 |
| FeatureManager Design Tree | 1-19 |
| Fly-out FeatureManager | 1-21 |
| Task Pane | 1-22 |
| Design Library | 1-22 |
| File Explore | 1-23 |
| Search | 1-23 |
| View Palette | 1-23 |
| Appearances, Scenes, and Decals | 1-24 |
| Custom Properties | 1-24 |
| Document Recovery | 1-24 |
| Motion Study tab | 1-25 |
| MotionManager | 1-25 |
| Animation | 1-25 |
| Basic Motion | 1-25 |
| System Options | 1-31 |
| Part Document Template and Document Properties | 1-32 |
| PLATE Part Overview | 1-35 |
| PLATE Part-New SolidWorks Document | 1-37 |

| | |
|--|------------|
| PLATE Base Feature | 1-38 |
| Machined Part | 1-39 |
| Reference Planes and Orthographic Projection | 1-40 |
| PLATE Part-Extruded Boss/Base Feature | 1-44 |
| PLATE Part-Modify Dimensions and Rename | 1-52 |
| Display Modes, View Modes, View tools, and Appearances | 1-54 |
| Fasteners | 1-56 |
| PLATE Part-Extruded Cut Feature | 1-58 |
| PLATE Part-Fillet Feature | 1-63 |
| PLATE Part-Hole Wizard | 1-65 |
| ROD Part Overview | 1-68 |
| ROD Part-Extruded Boss/Base Feature | 1-70 |
| ROD Part-Hole Wizard Feature | 1-72 |
| ROD Part-Chamfer Feature | 1-73 |
| ROD Part-Extruded Cut Feature & Convert Entities Sketch Tool | 1-74 |
| ROD Part-View Orientation, Named Views & Viewport option | 1-79 |
| ROD Part-Copy/Paste Function | 1-80 |
| ROD Part-Design Changes with Rollback Bar | 1-81 |
| ROD Part-Recover from Rebuild Errors | 1-83 |
| ROD Part-Edit Part Color | 1-87 |
| GUIDE Part Overview | 1-89 |
| GUIDE Part-Extruded Boss/Base Feature and Dynamic Mirror Feature | 1-91 |
| GUIDE Part-Extruded Cut Slot Profile | 1-94 |
| GUIDE Part-Mirror Feature | 1-98 |
| GUIDE Part-Holes | 1-99 |
| GUIDE PART-Linear Pattern Feature | 1-102 |
| GUIDE Part-Materials Editor and Mass Properties | 1-104 |
| Manufacturing Considerations | 1-106 |
| Sketch Entities and Sketch Tools | 1-109 |
| Project Summary | 1-110 |
| Project Terminology | 1-110 |
| Questions / Exercises | 1-114 |
| | |
| Project 2 - Fundamentals of Assembly Modeling | 2-1 |
| Project Objective | 2-3 |
| Project Situation | 2-4 |
| Project Overview | 2-5 |
| Bottom-up Assembly Modeling Approach | 2-5 |
| Linear Motion and Rotational Motion | 2-6 |
| GUIDE-ROD assembly | 2-7 |
| GUIDE-ROD assembly - Insert Components | 2-11 |
| FeatureManager Syntax | 2-13 |
| Mate Types | 2-16 |
| Standard Mates | 2-16 |
| Advanced Mates | 2-17 |
| Mechanical Mates | 2-17 |
| GUIDE-ROD Assembly - Mate the ROD Component | 2-18 |
| GUIDE-ROD Assembly - Mate the PLATE Component | 2-23 |
| GUIDE-ROD Assembly - Mate Errors | 2-27 |
| Collision Detection | 2-30 |
| Modify Component Dimension | 2-31 |

| | |
|---|------------|
| SolidWorks Design Library | 2-32 |
| GUIDE-ROD Assembly - Inert Mates for Flange bolts | 2-35 |
| Socket Head Cap Screw Part | 2-39 |
| SmartMates | 2-44 |
| Coincident/Concentric SmartMate | 2-44 |
| Tolerance and Fit | 2-47 |
| Exploded View | 2-51 |
| Section View | 2-56 |
| Analyze an Interference Problem | 2-58 |
| Save As Copy Option | 2-59 |
| GUIDE-ROD Assembly-Feature Driven Component Pattern | 2-62 |
| Redefining Mates and Linear Components Pattern | 2-64 |
| Folders and Suppressed Components | 2-68 |
| Make-Buy Decision | 2-69 |
| CUSTOMER Assembly | 2-71 |
| Copy the CUSTOMER Assembly - Pack and Go | 2-77 |
| Project Summary | 2-79 |
| Project Terminology | 2-80 |
| Questions / Exercises | 2-87 |
| | |
| Project 3 - Fundamentals of Drawing | 3-1 |
| Project Objective | 3-3 |
| Project Situation | 3-4 |
| Project Overview | 3-4 |
| Drawing Template and Sheet Format | 3-5 |
| Sheet Format and Title Block | 3-12 |
| Company Logo | 3-17 |
| Save Sheet Format and Save As Drawing Template | 3-19 |
| GUIDE Part-Modify | 3-22 |
| GUIDE Part - Drawing | 3-23 |
| Move Views and Properties of the Sheet | 3-26 |
| Auxiliary View, Section View and Detail View | 3-29 |
| Auxiliary View | 3-30 |
| Section View | 3-31 |
| Detail View | 3-32 |
| Partial Auxiliary View - Crop View | 3-33 |
| Display Modes and Performance | 3-35 |
| Detail Drawing | 3-37 |
| Move Dimensions in the Same View | 3-40 |
| Partial Auxiliary View-Crop View | 3-40 |
| Move Dimensions to a Different View | 3-44 |
| Dimension Holes and the Hole Callout | 3-45 |
| Center Marks and Centerlines | 3-48 |
| Modify the Dimension Scheme | 3-50 |
| GUIDE Part-Insert an Additional Feature | 3-54 |
| General Notes and Parametric Notes | 3-56 |
| Revision Table | 3-59 |
| Part Number and Document Properties | 3-61 |
| Exploded View | 3-67 |
| Balloons | 3-69 |
| Bill of Materials | 3-71 |

| | |
|---|------------|
| Project Summary | 3-76 |
| Project Terminology | 3-77 |
| Questions / Exercises | 3-80 |
| Project 4 - Extrude and Revolve Features | 4-1 |
| Project Objective | 4-3 |
| Project Overview | 4-4 |
| Design Intent | 4-6 |
| Project Situation | 4-9 |
| Part Template | 4-11 |
| BATTERY Part | 4-15 |
| BATTERY Part - Extruded Boss/Base Feature | 4-17 |
| BATTERY Part - Fillet Feature Edge | 4-22 |
| BATTERY Part - Extruded Cut Feature | 4-23 |
| BATTERY Part - Fillet Feature Face | 4-25 |
| BATTERY Part - Extruded Boss/Boss Feature | 4-27 |
| Injection Molded Process | 4-32 |
| BATTERYPLATE Part | 4-33 |
| Save As, Delete, Modify and Edit Feature | 4-34 |
| BATTERYPLATE Part - Extruded Boss/Base Feature | 4-36 |
| BATTERYPLATE Part - Fillet Features-Full Round, options | 4-37 |
| Multi-body Parts and the Extruded Boss/Base Feature | 4-40 |
| LENS Part | 4-42 |
| LENS Part-Revolved Base Feature | 4-43 |
| LENS Part-Shell Feature | 4-46 |
| Extruded Boss Feature and Convert Entities Sketch tool | 4-47 |
| LENS Part-Hole Wizard | 4-48 |
| LENS Part - Revolved Boss Thin Feature | 4-51 |
| LENS Part - Extruded Boss/Boss Feature and Offset Entities | 4-53 |
| LENS Part - Extruded Boss/Boss Feature and Transparent Optical Property | 4-55 |
| BULB Part | 4-57 |
| BULB Part - Revolved Base Feature | 4-58 |
| BULB Part - Revolved Boss Feature and Spline Sketch tool | 4-60 |
| BULB Part - Revolved Cut Thin Feature | 4-62 |
| BULB Part - Dome Feature | 4-64 |
| BULB Part - Circular Pattern Feature | 4-65 |
| Customizing Toolbars and Short Cut Keys | 4-69 |
| Design Checklist and Goals before Plastic Manufacturing | 4-71 |
| Mold Base | 4-73 |
| Applying SolidWorks Features for Mold Tooling Design | 4-74 |
| Manufacturing Design Issues | 4-83 |
| Project Summary | 4-84 |
| Project Terminology | 4-85 |
| Questions / Exercises | 4-89 |
| Project 5 - Swept, Lofted and Additional Features | 5-1 |
| Project Objective | 5-3 |
| Project Overview | 5-4 |
| Project Situation | 5-5 |
| O-RING Part - Swept Base Feature | 5-7 |

| | |
|--|------------|
| O-RING Part - Design Table | 5-9 |
| SWITCH Part - Lofted Base Feature | 5-13 |
| SWITCH Part - Dome Feature | 5-18 |
| Four Major Categories of Solid Features | 5-20 |
| LENSCAP Part | 5-20 |
| LENSCAP Part - Extruded Boss/Base, Extruded Cut and Shell Features | 5-21 |
| LENSCAP Part - Revolved Cut Thin Feature | 5-24 |
| LENSCAP Part - Thread, Swept Feature and Helix/Spiral Curve | 5-25 |
| HOUSING Part | 5-31 |
| HOUSING Part - Lofted Boss Feature | 5-34 |
| HOUSING Part - Second Extruded Boss/Base Feature | 5-38 |
| HOUSING Part - Shell Feature | 5-39 |
| HOUSING Part - Third Extruded Boss/Base Feature | 5-40 |
| HOUSING Part - Draft Feature | 5-41 |
| HOUSING Part - Thread with Swept Feature | 5-43 |
| HOUSING Part - Handle with Swept Feature | 5-48 |
| HOUSING Part - Extruded Cut Feature with Up To Surface | 5-53 |
| HOUSING Part - First Rib and Linear Pattern Feature | 5-55 |
| HOUSING Part - Second Rib Feature | 5-58 |
| HOUSING Part - Mirror Feature | 5-61 |
| FLASHLIGHT Assembly | 5-64 |
| Assembly Template | 5-65 |
| LENSANDBULB Sub-assembly | 5-65 |
| BATTERYANDPLATE Sub-assembly | 5-70 |
| CAPANLENS Sub-assembly | 5-72 |
| FLASHLIGHT Assembly | 5-76 |
| Addressing Interference Issues | 5-82 |
| Export Files and eDrawings | 5-83 |
| Project Summary | 5-86 |
| Project Terminology | 5-86 |
| Questions / Exercises | 5-89 |
| | |
| Project 6 - Top-Down Assembly Modeling and Sheet Metal | 6-1 |
| Project Objective | 6-3 |
| Project Situation | 6-4 |
| Top-Down Assembly Modeling | 6-5 |
| BOX Assembly Overview | 6-8 |
| InPlace Mates and In-Context features | 6-10 |
| Part Template and Assembly Template | 6-12 |
| Box Assembly and Layout Sketch | 6-13 |
| Global Values and Equations | 6-17 |
| MOTHERBOARD - Insert Component | 6-20 |
| POWERSUPPLY - Insert Component | 6-26 |
| Sheet Metal Overview | 6-34 |
| Bends | 6-34 |
| Relief | 6-37 |
| CABINET - Insert Component | 6-37 |
| CABINET - Rip Feature and Sheet Metal Bends | 6-40 |
| CABINET - Edge Flange | 6-42 |
| CABINET - Hole Wizard and Linear Pattern | 6-45 |
| CABINET - Sheetmetal Library Feature | 6-49 |

| | |
|---|------------|
| CABINET - Louver Forming tool | 6-53 |
| Manufacturing Considerations | 6-54 |
| Additional Pattern Options | 6-60 |
| CABINET - Formed and Flat States | 6-62 |
| CABINET - Sheet Metal Drawing with Configurations | 6-64 |
| PEM Fasteners and IGES Components | 6-70 |
| Derived Component Pattern | 6-74 |
| MOTHERBOARD - Assembly Hole Feature | 6-76 |
| Assembly FeatureManager and External References | 6-77 |
| Replace Components | 6-79 |
| Equations | 6-82 |
| Design Tables | 6-86 |
| BRACKET Part - Sheet Metal Features | 6-89 |
| BRACKET Part - In-Content Features | 6-91 |
| BRACKET Part - Edge, Tab, Break Corner and Miter Features | 6-93 |
| BRACKET Part - Mirror Component | 6-98 |
| MirrorBRACKET Part - Bends, Fold, Unfold and Jog Features | 6-102 |
| Project Summary | 6-106 |
| Project Terminology | 6-107 |
| Questions / Exercises | 6-109 |
| | |
| Project 7 - SimulationXpress, Sustainability and DFMXpress | 7-1 |
| Project Objective | 7-3 |
| SolidWorks SimulationXpress | 7-3 |
| SolidWorks SimulationXpress Wizard | 7-7 |
| Welcome | 7-7 |
| Fixtures | 7-7 |
| Loads | 7-8 |
| Materials | 7-8 |
| Run | 7-8 |
| Results | 7-8 |
| Optimize | 7-8 |
| Analyze the MGPMRod Part | 7-9 |
| Review of SolidWorks SimulationXpress | 7-12 |
| SolidWorks Sustainability | 7-13 |
| Life Cycle Assessment | 7-14 |
| Key Elements | 7-15 |
| Carbon Footprint | 7-16 |
| Energy Consumption | 7-16 |
| Air Acidification | 7-16 |
| Water Eutrophication | 7-16 |
| SustainabilityXpress Wizard | 7-15 |
| Material Class | 7-15 |
| Material Name | 7-15 |
| Manufacturing Process | 7-16 |
| Generate a Report | 7-17 |
| References - Sustainability | 7-18 |
| Methodology | 7-18 |
| SolidWorks DFMXpress | 7-26 |

| | |
|--|------------|
| DFMExpress Wizard | 7-26 |
| Run | 7-27 |
| Settings | 7-27 |
| Close | 7-27 |
| Help | 7-28 |
| Project Summary | 7-28 |
| Questions / Exercises | 7-28 |
| | |
| Project 8 - Intelligent Modeling Techniques | 8-1 |
| Project Objective | 8-3 |
| Design Intent | 8-4 |
| Sketch | 8-4 |
| Geometric relations | 8-4 |
| Full Defined Sketch tool | 8-5 |
| SketchXpert | 8-8 |
| Equations | 8-11 |
| Dimension driven equations | 8-11 |
| Equation Driven Curve | 8-14 |
| Explicit Driven Equation Curve | 8-14 |
| Parametric Driven Equation Curve | 8-16 |
| Curves | 8-18 |
| Curve Through XYZ Points | 8-19 |
| Projected Composite Curves | 8-21 |
| Feature - End Conditions | 8-23 |
| Along A Vector | 8-26 |
| FeatureXpert (Constant Radius) | 8-27 |
| Symmetry | 8-28 |
| Bodies to mirror | 8-28 |
| Planes | 8-30 |
| Conic Sections | 8-31 |
| Assembly | 8-32 |
| Assembly Visualization | 8-32 |
| SolidWorks Sustainability | 8-33 |
| MateXpert | 8-34 |
| Drawing | 8-34 |
| DimXpert | 8-35 |
| Summary | 8-35 |
| | |
| Appendix | A-1 |
| ECO Form | A-1 |
| Types of Decimal Dimensions (ASME Y14.5M) | A-1 |
| SolidWorks Keyboard Shortcuts | A-3 |
| Windows Shortcuts | A-3 |
| CSWA Certification Introduction | A-5 |
| Intended Audience | A-9 |
| Helpful On-Line information | A-10 |
| | |
| Index | I-1 |